

Company Name: Comfrey House RTM Company Limited

Inspector Name: K. Zak

Inspection Date: 10 October 2024

Purpose

This site inspection record is used when undertaking regular site inspections and is solely for the purpose of recording and monitoring the common (communal) parts on behalf of the above company.

What Is Included

The below report comments on the general condition of the interior and exterior communal parts (where applicable) as they were found at the time of this inspection.



Please note: This inspection is carried out visually by the property manager or a competent person instructed by the property manager and should not be used for any other purpose than to comment and record the general state and condition of the common (communal) parts that are inspected during a routine site visit. Where further investigation, testing or remedial work is required, a competent person is instructed by the property manager.



BLOCK MANAGEMENT LTD

PROFESSIONAL PROPERTY MANAGEMENT


Internal Inspection	Acceptable	Not Acceptable	N/A	Comments	Action
Entrances (Main doors)	✓				None
Hallway (Communal Lobbies and Stairs)	✓				None
Lighting (Standard and Emergency Lighting)	✓				None
Internal Doors (Compartment Doors)			✓		None
Cupboard Doors (Electrical Cupboard Doors)	✓				None
Windows (Communal Windows)	✓				None
Signage (Communal Notices)	✓				None
Additional Comments					None



BLOCK MANAGEMENT LTD

PROFESSIONAL PROPERTY MANAGEMENT

External Inspection	Acceptable	Not Acceptable	N/A	Comments	Action
Exterior Structure (The Building)	✓				None
Guttering (Gutters and Fascia)	✓				None
Roofing (Tiles and Cladding)	✓				None
Communal Grounds (Gardens and Common Areas)	✓				None
Bin Store (Waste Disposal Areas)	✓				None
Car Park (Vehicle Parking)	✓				None
Bike Store (Bicycle Areas)			✓		None
Additional Comments					None

Entrances (Main Doors)	Hallway (Communal Lobbies and Stairs)	Lighting (Standard and Emergency Lights)	Internal Doors (Compartment Doors)
 A photograph of a white entrance door with a small window and a silver handle. To the right of the door is a set of white mailboxes. The floor is covered with a dark blue mat.	 A photograph of a hallway with a red carpet. On the right, there is a staircase with a wooden handrail and a glass balustrade. On the left, there are white mailboxes and a notice board.	 A photograph of a circular, recessed ceiling light fixture in a room with a perforated acoustic ceiling.	
Cupboard Doors (Electrical Cupboard Doors)	Windows (Communal Windows)	Signage (Communal Notices)	Additional Photos
 A photograph of a white cupboard door with a yellow warning sign (a triangle with an exclamation mark) and a blue circular sign. The door is set in a hallway.	 A photograph of a large window with a view of a red brick building and a street. The window is set in a room with a red carpet.	 A photograph of a notice board on a wall. The board contains several notices and signs, including a 'No Smoking' sign. There are also some items on a small white table in front of the board.	

Exterior Structure (The Building)	Guttering (Gutters and Fascia)	Roofing (Tiles and Cladding)	Communal Grounds (Gardens and Common Areas)
			
Bin Store (Waste Disposal Area)	Car Park (Vehicle Parking)	Bike Store (Bicycle Areas)	Additional Photos
